

WSN9 workshop campaign - Replacing the plastic slide of the front three-point seat-belt

WSN9 workshop campaign - Replacing the plastic slide of the front three-point seat-belt

ID Number	WSN9
Model(s)	Macan (XAB)
Model Year(s)	2024 - 2026
Number of Affected VINs	11,356
VIN List	Attached
Issue Description	On the affected vehicles, there is a possibility that rattling noises could occur on the B-pillar on the passenger side due to the free-swinging belt tongue of the three-point seat-belt. To prevent noise complaints, the plastic slide on the three-point seat-belt on the passenger side must be replaced by a plastic slide with belt loop.
What Porsche Centers Should Do	Please arrange for this action to be carried out on the affected vehicles during the next workshop visit or before the vehicles are handed over to customers. (Solution available as of 10/20/2025)
TI	WSN9
Part Status	Status 1 - Order as needed

Required parts

V04015858 RAA	Belt loop, black	1 unit
---------------	------------------	--------

Warranty processing

Validity:

The present workshop campaign is carried out by the date maintained in PCSS and then closed

Please note that warranty claims can only be processed up to this date.

WSN9 workshop campaign - Replacing the plastic slide of the front three-point seat-belt

Scope 1:

Damage Code	WSN9 66 000
Repair Code	2
Labor time	19 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Attachments

1. [WSN9 WS Camp VIN List for Field Managers V3 10.17.2025 HT.xlsx](#)