

Technical Service Bulletin

Topic	91 MIB3 - Radio plays when vehicle is parked (Q4)
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2079597/1
Level	EH
Status	Released for publishing
Release date	Oct 7, 2025

New customer code

Object of complaint	Complaint type	Position
information, navigation, communication, entertainment -> radio operation	functionality	
information, navigation, communication, entertainment -> radio, navigation, MMI and drive device functions -> switch device\MMI on\off	functionality -> switches on by itself	

Vehicle data

MIB3 - Cluster 37

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
F4*	2022	A		*	*	*
F4*	2023	A		*	*	*
F4*	2024	A		*	*	*

Control units

Diagnostic address	Software part number	Software version	Hardware part number	Hardware version
0075 - Emergency call module and communication unit	*	0556	*	*
0075 - Emergency call module and communication unit	*	0664	*	*
0075 - Emergency call module and communication unit	*	0686	*	*
0075 - Emergency call module and communication unit	*	0538	*	*
0075 - Emergency call module and communication unit	*	B716	*	*

Documents

Document name
master.xml
attachment1.jpg

Condition

Customer states:

The customer complains that the radio plays when the vehicle is parked.

When this occurs, the screen is sometimes black.

When the driver's side door is opened, the radio usually stops.

Workshop findings:

The complaint occurs only sporadically and can therefore be difficult to reproduce.

Technical Background

Software issue in control unit 1 for information electronics (005F).

Production Solution

New software installed in production as of week 45/2023.

Service

This TSB replaces Pending Service Solution (PSS) 2074400, (*PSS 91 MIB3: radio plays when vehicle is parked*).

Update the MMI software following directions in TSB 2079289, *Combined software update ID.S 3.8.2 for Audi Q4*.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9196		
Damage Code:	0039		
Labor Operations:	Software update flat rate incl. additional work and adaptation drives	0151 0040	60 TU
	Charge battery	2706 8950	See SRT with associated operations
Claim Comment:	As per TSB 2079597/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please

inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle's software). Please inform the customer that this software update may neutralize previous modifications to the vehicle's software performed either by the customer or other third parties.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2079597**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.