



Service Bulletin

Bulletin No.: PIC6628B

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Windshield to Dash Valence Foam Seal Mis-positioned

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2025 - 2026		All	All	All	All

Involved Region or Country	North America, Canada, Mexico
Condition	Customers may comment that the foam seal at the base of the windshield, will be visible from either the outside of windshield or from inside the interior when looking at the front of the instrument panel.
Cause	Engineering is currently investigating.

Correction

Confirm condition exists, see example below.

In the meantime, please advise customer they may continue to drive the vehicle.

The PI will be updated or replaced with a TSB once a determination has been made.



7012512

Version	1
Modified	10/23/2025 - Created On.

