

206 C43 AMG - Speakers/front bass in the footwell not functioning (without SA810)

Topic number	LI82.62-P-079964
Version	1
Function group	82.62 - Loudspeakers, amplifiers, antennas
Date	11/3/25
Validity	206 C43 AMG - 206.087 & 206.287 - without SA 810
Reason for change	

Complaint

Frontbass in the driver's and/or front passenger side's footwell not functioning.

Cause

Overload in the critical limits at high volume and strong bass setting.

Remedy

Replacement of the speakers on both sides with the more robust versions:


A2548202301 Front bass left

A2068206601 Front bass right

Note:

In some cases, the locking mechanism of the plug must be reworked. To do this, remove the area marked in red in the attachment using a suitable tool.

Attachments	
File	Description
Stecker Typ A Standard Soundsystem.png	Marking the locking mechanism to be removed



Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms
Communication/information > Entertainment > Audio/Sound > Speakers emit no sound
Communication/information > Entertainment > Audio/Sound > Speakers emit interference noise
Communication/information > Entertainment > Audio/Sound > Poor audio quality
Communication/information > Entertainment > Audio/Sound > Several speakers are nonfunctional
Communication/information > Entertainment > Audio/Sound > Misfire

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
		H	87A05	Please use this damage code for warranty claims.