



PERSONAL SERVICE LAB

MASTERS OF CARE

Grecale Cold Start Exhaust Metallic Noise

IMPORTANT NOTICE This bulletin supersedes **MAS004812 MTB 25-27** released on **July 15, 2025**. It contains updated information, please ensure all previous versions are discarded.

DATE: November 19, 2025

This bulletin provides updated information regarding the metallic noise originating from the exhaust system on Grecale MHEV models during cold starts. The issue is related to exhaust valve behavior and has been resolved with a now available software update.

Affected Model & System

- Model: Grecale (M182) – MHEV engine only (All MY)
- System Section: 01.81-1 – Silencers

ACTIONS:

- Do not replace the exhaust system and do not dismount the flap valve.
- Proceed with ECM Software update using the EVO.

Verify that the issue is repaired, if not, open a BOL report for Technical Support attaching video of the issue.

Warranty Claim

Use the following codes for the warranty claim:

Description	Code
Component Code	1.90.001
ECM SW update	1.90.001.9 (0,20 h)

NOTE: Maserati reserves the right to modify or cancel claims that do not meet the criteria outlined in this communication.

We remain at your disposal for clarifications.

Best regards,

TECHNICAL SERVICE OPERATIONS