

Bulletin #: C32-1125-0658		☐ Take Note ☒ Take Action	
☐ Retail Operator	☐ Sales Pre-Owned	☐ Business Manager	☒ Parts & Accessories
☐ General Manager	☐ Sales New Car	☐ Service	☐ Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: November 18, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC806 REAR GLASS RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

51 31 7 195 333

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing antenna cable installed incorrectly. Parts with cable installed correctly are ok for use. Please see images below for details.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC806 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC806 is valid from November 18, 2025, through December 02, 2025. The deadline for filing a claim under TEC806 is December 02, 2025. All parts must be returned to your facing RDC no later than December 16, 2025.

Please reorder the same part number as needed.

