

Bulletin #: C32-1125-0659		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: November 20, 2025		Supersedes:	



# BMW PARTS BULLETIN

## TEC807 LEFT DOOR COVER RETURN

### TAKE ACTION

BMW AG has requested the inspection and return of the following affected part number:

51 41 5 B4C 8F1

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far missing the light element. Parts containing the light element are ok for use. Please see images below for details.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC807 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC807 is valid from November 20, 2025, through December 04, 2025. The deadline for filing a claim under TEC807 is December 04, 2025. All parts must be returned to your facing RDC no later than December 18, 2025.

Please reorder the same part number as needed.

