

Update Title	GM Update 652.30
Associated Field Action Number(s)	N25-250322
Release notes	<p>Improvements to Apple CarPlay performance.</p> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2025
Make	Chevrolet GMC
Model	Equinox Terrain
Components	VCU (Vehicle Cockpit Unit)