

Update Title	GM Update 654.10
Associated Field Action Number(s)	N25-250322
Release notes	<ul style="list-style-type: none">• Improvements to Apple CarPlay performance. <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2025
Make	Buick
Model	Envision
Components	VCU (Vehicle Cockpit Unit)