

Update Title	GM Update 654.20
Associated Field Action Number(s)	N25-250179
Release notes	<ul style="list-style-type: none"> • Fixes to help prevent battery drain. • Fixes to responsiveness issues with Wi-Fi, Navigation, Super Cruise, and OnStar. • Improvements to software updates. • Improvements to OnStar emergency calls. • Fixes to address cellular connectivity issues. <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2024
Make	Buick
Model	Envision
Components	TCP (Telematics Communication Platform)