

[📄 25-01-061H-1 - DCU Software Update \(Service Campaign TDFC\)\\_\(Posted 11.25.25\).pdf](#)

## Hyundai Motor America (HMA) has re-launched Campaign TDFC for the DCU Software Update!

**Technical Service Bulletin (TSB) Update: This TSB supersedes 25-01-061H to add additional information for VCI 2 connection and IP settings on pages 4-5.**

### **A. Affected Vehicles:**

- Certain 2025-2026MY Tucson (NX4A) produced from 06/20/2024 – 08/13/2025

- VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine campaign applicability.

### **B. Campaign Description:**

Certain Tucson (NX4A) vehicles may exhibit a Data Communication Unit (DCU) software error due to the internal timer initialization logic not being implemented. The DCU module may shut down telematics services after one year. **TSB 25-01-061H-1** provides instructions to perform a software update for the DCU module.

**Over-the-Air (OTA)**: This update can also be conducted via OTA. The customer can complete on his/her own if he/she has an active subscription to Hyundai Bluelink. A visit to the dealership is not required.

### **C. Campaign Document(s):**

#### **1. TSB 25-01-061H-1; supersedes TSB 25-01-061H**

- Available on [Hyundaidealer.com](https://hyundaidealer.com) > Service > HMA Tech Info > Campaign

### **D. Action Required:**

1. Confirm VIN eligibility for campaign via WebDCS.
2. **Follow the TSB** for the service procedure to update the software.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America