

 Preview Solution CBR-2528-1

Mack Chassis - PR (4) - Pioneer Bug Screen Hitting Bumper

Published 13 November 2025

Valid For

Mack Chassis - PR(4)

Model Year - 2025 to current

The purpose of this CBR is to address reports of the bug screen behind the grill hitting the bumper.


Parts Needed

Part Number	Description	QTY
948702	CABLE TIE	3

Note: May use any zip tie that is equivalent to 948702/

Procedure

1. Open hood to access the bottom of the grill.
2. Use cable tie listed in parts needed to secure the bottom of bug shield to bottom of the grill



3. Secure in a fashion so that the cable tie head does not hit the bumper.



4. Check for if the bug shield is still hitting the bumper, if so please use IMPACT operation 8611-05-02-01 Front Bumper, Adjustment.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article