



Service Bulletin

Bulletin No.: PIT6460

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Sensor Not Compatible Message When Performing TPM Sensor Learn with EL-52545

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Terrain	2025 - 2026		All	All	All	All

Involved Region or Country	United States, Canada, Mexico, Middle East
Condition	A dealer may report that they cannot learn the Tire Pressure Monitoring Sensors (TPMS) and get a Sensor not compatible message from the EL-52545 TPMS Tool.
Cause	This is due to a software issue in the last release for the TPMS tool (EL-52545) that seems to only effect the 2025-26 Terrain models. The tool supplier has been made aware and will make an update.

Correction

Version	1
Modified	11/25/2025 — Created.

