



Mitsubishi Motors North America, Inc.
TECHNICAL INFORMATION NOTICE

SUBJECT:

**Abnormal Noise/Vibration from Rear
Differential Assembly**

No: TIN-25-27-001

Version: 1

Date: November 4, 2025

TO: Service Managers, Service Advisors, Parts Managers, Technicians and Warranty Administrators

AFFECTED VEHICLES:

Certain 2024 Outlander (produced after June 18, 2024)
All 2025 Outlander

PURPOSE:

MMNA is investigating reports of rear differential concerns on vehicles where TSB-25-27-001 does not apply because the vehicle was manufactured after the VIN cutoff (JA4J4VA86RZ077680 / June 18, 2024).

DEALER ACTION REQUIRED:

1. Do not proceed with any rear differential repairs or fluid service if the vehicle falls outside of TSB-25-27-001 (VIN cutoff JA4J4VA86RZ077680 / June 18, 2024).
2. Contact Tech Line for guidance before initiating any rear differential repairs if the vehicle was produced after the VIN cutoff (JA4J4VA86RZ077680 / June 18, 2024).