



# Service Bulletin

Bulletin No.: PIT6345A

Date: December, 2025

## PRELIMINARY INFORMATION

**Subject: P059F and P05AE DTCs set in snowy or icing conditions Proactive**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025		All	All	All	All
GMC	Terrain	2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Vehicle may present with a CEL and DTCs P059F and P05AE.
<b>Cause</b>	This is likely caused by a software anomaly mixed with snow or freezing temperatures.

### Correction

If no issue is found after completing the diagnostics in SI for both DTCs, do not replace the shutter assembly.

Engineering is currently investigating.

The PI will be updated or replaced with TSB once a determination has been made.

<b>Version</b>	1
<b>Modified</b>	02/21/2025 – Created on.

