



STAR ONLINE PUBLICATION



Case Number: S2523000090

Release Date: December 2025

Symptom/Vehicle Issue: MOPAR Bed Divider Kit Missing Lock Cylinder

Customer Complaint/Technician Observation: Owner has purchased 68402268AC MOPAR Bed Divider Kit and the kit is missing the lock cylinder.

Discussion: Kits sold after 8/23/2022 no longer are equipped with the lock cylinder. Adding one is not a warrantable concern. This was announced in warranty bulletin Vol 9 published 8-Nov-2023. This applies to all Bed Divider kits installed on 2023-2025 Models.

Bed Divider Lock Cylinder Elimination - MY 2022 DT

Since 2022 model year, DT vehicles have not had and will no longer have the following part numbers for **Bed Divider Lock Cylinder** as part of their equipment: **68312242AE** and **68438041AA**

The above part numbers have no other part number that replaced them. The elimination of the Bed Divider Lock Cylinder was implemented since 08/23/22 triggered by a Complexity Reduction Request from the program team.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.