

# V O L V O

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title DTCs in Cars without FLL		Ref. No. TJ 37588.1.0	
Issuer (Dept.) Technical Service		Issue Date 11/13/25	Status Date 11/18/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3884	
Function Description Autonomous drive lidar		Page Page 1 of 2	

### DESCRIPTION:

This is for vehicles without an FLL.

If a vehicle has one or more of DTC(s) listed below set, follow the advice under "Service".

### CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use
2V	Technician information/Software/Vehicle communication/Not for warranty use

### DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
HPB	U14AB87	Permanent
HPB	U14AB46	Permanent
HPB	U14AB54	Permanent
HPB	B198B54	Permanent
HPB	U365A00	Permanent
HPB	U365A13	Permanent
HPB	U14AB56	Intermittent
HPB	U14AB57	Intermittent
HPB	U14AB8C	Intermittent
HPB	U14AB92	Intermittent
HPB	B198B46	Intermittent

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
334							2026-2026		-	202546-202617
356							2026-2026		-	202546-202617

## Technical Journal 37588.1.0

---

### **SERVICE:**

Ignore the stated DTCs; nothing needs to be done. The DTCs have no actual impact on the vehicle's functionality.

### **Abbreviations:**

FLL = Forward Looking Lidar

### **Warranty claim info:**

No warranty claim is accepted for this TJ or for the operation to clear this DTC.

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3884.