

<b>Update Title</b>	GM Update 625.41
<b>Associated Field Action Number(s)</b>	N25-251815 N25-253034
<b>Release notes</b>	<ul style="list-style-type: none"> <li>• Improvements to availability of Lane Keep Assist.</li> <li>• Fixes to help ensure safety features remain functional when windshield freezes.</li> <li>• Fixes to diagnostics that impact Automatic Emergency Braking indicator.</li> <li>• Fixes to help protect battery life.</li> <li>• Fixes to help prevent loss of Performance Data Recorder functionality</li> </ul> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
<b>Model Year</b>	2024 2025
<b>Make</b>	Chevrolet
<b>Model</b>	Corvette
<b>Components</b>	FCM (Front Camera Module) PDR (Performance Data Recorder)