



SIB 61 11 25

SERVICE ACTION: Replace Reverser Control Unit

2025-12-22

MODEL

Model	Model Description	Model Code
K48 GT	K 1600 GT	0F23
K48 GTL	K 1600 GTL	0F33
K61	K 1600 Bagger	0F63

The affected vehicles have been marked with campaign number **0061720000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

After quality inspection it has been found that the reverser control unit PN 61 35 8 524 078 was installed on a number of units. This specific control unit was inadequately manufactured leaving a possibility of corrosion that could lead to the reverser function failing particularly in more humid climates.

For vehicles that have not yet been delivered, the service action must be completed before vehicle handover.

In all instances in which the vehicles have already been handed over to customers, the Technical Campaign must be performed at the next workshop visit.

The affected vehicles have been placed under the delivery stop **STOP610031** associated with campaign number 0061720000, which will be lifted upon completion of this technical campaign.

PROCEDURE

The reverser control unit must be replaced with the new control unit with part number (61 35 5 B5C 706) according to the repair instructions in AIR "61 35 100 – Replace the reverser control unit".

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in ETK which takes into account specific equipment and/or options.

Additional parts like gaskets, hardware, and chemicals may be required for the complete repair.

Part Number

61 35 5 B5C 706	Reverser Control unit
-----------------	-----------------------

NOTE: Please be considerate of other dealers when ordering these parts and order only the quantities you truly need, as stock may be limited. Thank you for your understanding.

Copyright ©2025 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved

CLAIM INFORMATION

Please submit claims via the normal claim process using the information below:

Defect code

00 61 72 00 00	Replace Reverser Control Unit
----------------	-------------------------------

K 1600 GT

Labor Operation

61 35 100	Replace Reverser Control Unit	10 FRU
+61 35 600	Replace Reverser Control Unit	9 FRU

K 1600 GTL and K 1600 Bagger

Labor Operation

61 35 100	Replace Reverser Control Unit	11 FRU
+61 35 600	Replace Reverser Control Unit	10 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 61 35 100 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 61 11 25 SA - Replace Reverser Control Unit.pdf](#)

