

46-024: CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

12/30/2025

[Edit](#) [Clone](#)

46-024

Subject

CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

Whats New Abstract

Certain Battery Electric Vehicles that are subject to California Air Resources Board (CARB) regulations have Vehicle Emissions Control Information (VECI) labels that are missing the CARB Enhanced EV and FCEV Statement.

Condition

The VECI label on affected chassis must be replaced to ensure compliance with regulatory standards.

While this bulletin does not expire, the deadline for completing this label replacement is 02/09/2026.

Chassis Affected

126 US vehicle model year 2024-2026 Model 579 / 537 / 520 / 220 Battery Electric Vehicles built from 04/26/2023 through 03/19/2025 that are subject to CARB regulations.


Action

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select campaign **46-024** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service

Management.

3. If you are not using Service Management to start repair orders, review SIR for Complete next to the **46-024** campaign code prior to performing this repair.
4. Follow the procedures in the Links section to remove and replace the VECI label.

 NOTE
Be aware that it may take from 2 to 4 weeks to receive the VECI label.

Warranty

Starting on **12/30/2025** Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:


- **0.3 hours** to remove and replace the VECI label and take photos of the old and new labels per the bulletin procedures. Use Recommended Repair Code **46-024**.
- File an additional claim for extraordinary circumstances. A recommended repair for standard labor must be filed first.

- File the claim within 14 days in accordance with the Warranty Policy.

PRWS CLAIM CODING			
Campaign Code:	46-024	Campaign Type:	Field Repair
Claim Category:	Truck	Repair Type:	Proactive
Customer Concern Code:	226	Causal Code:	00
Corrective Action Code:	03	Responsibility Code:	CAMP
Failure Location:	044-015-014	Causal Part:	S53-6198
Supplier Code:	N/A	SRT Code:	B25-41A 0.3 hours Replace Vehicle Emissions Control Information (VECI) label per bulletin procedure.

Parts

See the procedure in the Links section for instructions on ordering the VECI label.

 NOTE
Be aware that it may take from 2 to 4 weeks to receive the VECI label.

Quantity	Part Number	Description
1	S53-6198	VECI Label

Procedure



WARNING!

Follow your dealership's safety procedures and precautions to ensure the vehicle is safely repaired and maintained.

Read all procedure steps before beginning the repair.

Please see the Links section below for procedures on removing and replacing the VECI label.

Attachments

CHASSIS LIST

[46-024 PB Chassis List](#)

REPAIR PROCEDURE

[46-024 Repair Procedure](#)

CUSTOMER LETTER

[46-024 PB Customer Letter](#)



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

XX/XX/2025

Subject: 46-024: CARB Enhanced Electric Vehicle (EV) and Fuel Cell Electric Vehicle (FCEV) Statement

Expiration Date: None



FIELD SERVICE CAMPAIGN

This notice applies to your vehicle(s) with VIN(s) listed at the bottom or back of this page.

Dear Peterbilt Customer,

Peterbilt Motors Company has determined that certain Model 579, 537, 520, and 220 Battery Electric Vehicles built from 04/26/2023 through 03/19/2025 have Vehicle Emissions Control Information (VECI) labels that are missing the CARB Enhanced EV and FCEV Statement. This label must be replaced to ensure compliance with regulatory standards.

It is recommended to complete this label replacement no later than 02/09/2026.

What is the problem?	Certain Battery Electric Vehicles have a VECI label that is missing the CARB Enhanced EV and FCEV Statement, which is required for regulatory compliance.
What will your dealer do?	Replace the VECI label.
What should you do?	Contact your dealer to schedule a repair appointment.

To locate your nearest dealer please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When scheduling this service, please refer to campaign 46-024: CARB Enhanced EV and FCEV Statement and the VIN(s) listed in this letter. This service may require up to 1 hour of labor. There will be no charge to you for this label replacement.

If you no longer own the vehicle(s), please send an e-mail to servicebulletins@paccar.com with the complete VIN(s) and the name and address of the new owner.

We appreciate your attention to this matter and value your loyalty to Peterbilt and its dealer network.

Sincerely,
Peterbilt Customer Service