

Technical Service Bulletin

Topic	Bentayga - TPMs DTC 11F0F0 - Static Calibration at PDI
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2076738/3
Level	EH
Status	Released for publishing
Release date	Dec 10, 2025

New customer code

Object of complaint	Complaint type	Position
chassis -> tire monitoring	functionality	

Vehicle data

25MY Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2025	E		*	*	*
4V1*	2026	E		*	*	*
ZV1*	2025	E		*	*	*

Documents

Document name
master.xml

Condition

Tyre pressure monitoring yellow warning light in the driver instrument panel at PDI (Figure 1).



Figure 1

During the road test, the vehicle is unable to learn the tyre pressures.

Technical Background

This warning light may be caused by DTC 11F0F0: Static calibration (end of assembly line). This will be stored in diagnostic address 0065, tyre pressure monitoring system control module (Figure 2).

Address: 0065 System name: 0065 - Tire pressure monitoring Protocol variant: UDS/ISOTP (Events: 1)	
Identification:	
Event memory entries:	
Entry in fault memory	
Number:	C11F0F0: Static calibration (end of assembly line)
	active
Fault type 2:	active/static
Symptom:	49240
Status:	10101111

Figure 2

The tyre pressure monitoring system cannot be reset using ODIS Service.

Production Solution

Not applicable

Service

If the specified DTC occurs at PDI, please raise a full technical DISS to report the occurrence. Then order and replace the tyre pressure monitoring system control module.

Warranty

Warranty Type – 110 or 910

Damage Service Number – 44 34

Damage Code – 00 10

Removal and refitting of the Tyre Pressure Monitoring System Control Module

Labour Operation Code – 44 34 19 00

Time – 10 TU

Diagnostic Time

Labour Operation Code – 01 50 00 00

Time – As per ODIS log (must not exceed 50 TU)

Required Parts and Tools

For all part numbers please refer to the ETKA parts catalogue.