

# Technical Journal

TITLE:

**GHCA Fault Diagnosis and Replacement VST Operation**

<b>REF NO:</b> <b>TJ 37630.3.0</b>	<b>ISSUING DEPARTMENT:</b> <b>BBURGARD - Brian Burgard</b>	<b>CAR MARKET:</b> <b>United States and Canada</b>	
<b>PARTNER:</b> <b>3 US 7510 Volvo Car USA, LLC</b>		<b>ISSUE DATE:</b> <b>2025-12-19</b>	<b>STATUS DATE:</b> <b>2025-12-19</b>
<b>FUNC GROUP:</b> <b>3234</b>	<b>FUNC DESC:</b> <b>onboard charger, high voltage</b>	<b>Page 1 of 3</b>	

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## DESCRIPTION:

\* VST operation numbers updated.

\* Additional DTCs added.

If a vehicle shows the symptom of not being able to charge the HV battery via AC Charging, please follow the advice under "Service".

## CSC Customer Symptom Codes

Code	Description
YN	High voltage battery/Discharged/poor charge
YM	On board charger/No/reduced/incorrect function/While driving
YL	Plug-in charging/No/reduced/incorrect function/With external AC-cable
YZ	Plug-in charging/No/reduced/incorrect function/With external DC-cable
YW	Charging socket/LED indicates fault/reduced charging/Unsure when/at all times

# Technical Journal 37630.3.0

## DTC Diagnostic Trouble Codes

ECU	DTC	Fault Type
GHCA	B3A1D19	Permanent
GHCA	B3A1D47	Permanent
GHCA	B3A1D56	Permanent
GHCA	B3A1D78	Permanent
GHCA	P06AB11	Permanent
GHCA	P0D2600	Permanent
GHCA	P0E8592	Permanent
GHCA	P0E8B16	Permanent
GHCA	P0E8B68	Permanent
GHCA	P29BC16	Permanent
GHCA	P29BC98	Permanent
GHCA	P2DB701	Permanent
GHCA	P2E2F17	Permanent
GHCA	P2E9117	Permanent
GHCA	P2E9119	Permanent
GHCA	U359116	Permanent
GHCA	U359192	Permanent
GHCA	U35C794	Permanent
GCCC	U01BB00	Permanent
GHCA	B3A1D04	Permanent

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
359							2025-2099		-	202402-209952

### SERVICE:

#### Confirm the following:

1. DC charging still works; only AC charging does not.
2. One of the DTCs mentioned in this TJ is set.

If both criteria are fulfilled, proceed with this TJ. Otherwise, continue with VIDA fault tracing.

#### Task to perform:

Replace the GHCA according to VIDA.

#### Abbreviations:

AC - Alternating Current

DC - Direct Current

GHCA - Grid to High voltage Converter A

**Failing Part:** GHCA

# Technical Journal 37630.3.0

**Warranty claim info:**

To get a warranty claim accepted for a job described in this TJ, use only the corresponding VST OP number stated in this TJ.

Please note that fault tracing is not eligible for separate reimbursement under this TJ. Any fault tracing VST operation numbers will be rejected.

Note that the TJ number must be stated in the repair order text.

**VST Operation Number**

VST Operation NO.	Description
98821-3	Software download acc. to TJ
98786-2	GHCA replace acc. to TJ
97733-3	High voltage battery disconnect/connect and insulations measurement acc. QB/TJ
98801-2	General reimbursement acc. to TJ

**LABOR TIME:**

Labor time subject to change without notice.

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use the concern area "Vehicle Report Polestar" and the sub-concern area "Support Needed Polestar", use function group 3234.