

Heater Core Plugging

Issue Description Poor performance of primary HVAC heater

Status & Details Plugging noted of front HVAC heater core.

Chem lab results pending of returned samples

Field Action Monitor /report new instances
Review cooling system maintenance & repairs, 3rd party coolant system integrations, etc

Identifying Features

Reference Documentation

Additional Information VCC T1001837R

