
Reference	SSM000016
Models	New Range Rover / L460 2022 → Onwards
Title	Foul Odor Within the Passenger Compartment
Category	Non Technical
Last modified	19-Dec-2025 13:46:00

Content	<p>Title</p> <p>Foul Odor Within the Passenger Compartment</p> <p>SSM000016 (Land Rover)</p> <p>Markets:</p> <p>NAS, MENA</p> <p>Model / Model Year / Derivative</p> <p>Range Rover / 22MY onwards / vehicles with Perlino leather seat covers only</p> <p>Situation:</p> <p>JLR Engineering investigations have received reports of a foul odor coming from within the passenger compartment on certain vehicles manufactured with Perlino leather seat covers.</p> <p>Cause:</p> <p>Engineering are still determining root cause of this concern.</p> <p>Action:</p> <p>Refer to the service information below.</p> <p>Service Request:</p> <ol style="list-style-type: none">1. DO NOT renew any components for this concern.2. Raise a Technical Assistance (TA) which must include the below information:<ul style="list-style-type: none">- Reference to BES_202- Reference to P394611- Reference to this SSM000016 <p>The relevant Engineering team will provide further guidance.</p> <p>(Ref 000394611 / 000016)</p>
----------------	--

amF8cmH0zlwMJYIMDEIMDHUMTg5MT16MEuNTA4Wjs2Ni4xOTgUMTgxLJlwOTs=