



Service Bulletin

Bulletin No.: PIP6096

Date: January, 2026

PRELIMINARY INFORMATION

Subject: LSD Replacement Engine PCV Casting Design Change

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2023-2026		All	All	1.5 LSD	All
GM	Terrain	2023-2026		All	All	1.5 LSD	All

Involved Region or Country	North America
Condition	Technicians may notice a difference in the camshaft cover on a replacement engine
Cause	Starting in 2025, there was a design change to the PCV system on RPO LSD. Replacement engines will come equipped with the new (2025/2026) camshaft cover. In the event a 2023 or 2024 is being serviced please refer to the procedure below.

Correction

If the engine had catastrophic failure, metal in the oil, or severe sludge replace the camshaft cover per GM EPC for the VIN being serviced.

If the engine was replaced for other reasons than above clean and swap the cover from the engine being replaced being mindful of the PCV orifice not being dislodged.

Version	1
Modified	01/12/2026 Created on

