

CUSTOMER SATISFACTION NOTIFICATION

NORTH AMERICA

Oil Pump



FCA US LLC

Reference: 47B



2023 - 2024 (WS) Wagoneer/Grand Wagoneer

Template Version 1.8

Revision	Edition	Detail
2	January 2026	Labor time reduced for oil pump replacement and 4x4 equipped opt. eqp.

SYMPTOM DESCRIPTION

The oil pump on about 44 of the above vehicles may have an incorrectly installed spring which can dislodge and cause oil starvation to the engine, resulting in a no start condition.

SCOPE

This campaign applies only to the above vehicles equipped with a 3.0L GMET6 engine.

NOTE: Some vehicles above may have been identified as not involved in this campaign and therefore have been excluded from this campaign.

IMPORTANT: Some of the involved vehicles may be in dealer new vehicle inventory. Dealers should complete this campaign service on these vehicles before retail delivery. Dealers should also perform this repair on vehicles in used vehicle inventory and those vehicles in for service. Involved vehicles can be determined by using the VIP inquiry process.

REPAIR TO BE PERFORMED

Replace the Oil Pump by following the directions outlined in Service Library.

ALTERNATE TRANSPORTATION

Dealers should attempt to minimize customer inconvenience by placing the owner in a loaner vehicle if the vehicle must be held overnight.

Use the following labor operation numbers and time allowances:

Labor Description	Number	Hrs.
Replace Oil Pump	09-47-B1-82	5.5
Optional Equipment		
Air Suspension equipped	09-47-B1-61	0.4
4x4 equipped	09-47-B1-62	1.7
Additional Services		Allowance
Rental Vehicle	95-40-00-41	*\$80 per day

*Maximum 15 days

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete claim processing instructions.

PARTS INFORMATION

Qty	Part Name	Part No.
1	Oil Pump 3.0L SO	68358479AH
1	Oil Pump 3.0L HO	68585094AF
1	O-Ring Oil Pickup Tube	68374054AB
2	Seal, Oil Pan to Block	68359147AC
1	Gasket Oil Pan	68359145AC
1	Oil Filter	68466307AB
8	Oil, 0W20 Quart	68523994AA
1	Bolt, Driveshaft to Front Pinion (MSQ4)	06506497AA
1	Bolt, Driveshaft to Rear Pinion (MSQ4)	06506497AA
1	RTV Equivalent	NP

PARTS RETURN

No parts return required for this campaign.

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select "Global Recall System" on the Service tab, then click on the description of this notification.

CUSTOMER SATISFACTION NOTIFICATION

NORTH AMERICA

Oil Pump



FCA US LLC

Reference: 47B

Owner Notification and Service Scheduling

All involved vehicle owners known to FCA are being notified of the service requirement by mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

Vehicle Lists, Global Recall System, VIP and Dealer Follow Up

All involved vehicles have been entered into the DealerCONNECT Global Recall System (GRS) and Vehicle Information Plus (VIP) for dealer inquiry as needed.

GRS provides involved dealers with an updated VIN list of their incomplete vehicles. The owner's name, address and phone number are listed if known. Completed vehicles are removed from GRS within several days of repair claim submission.

To use this system, click on the "**Service**" tab and then click on "**Global Recall System.**" Your dealer's VIN list for each campaign displayed can be sorted by: those vehicles that were unsold at campaign launch, those with a phone number, city, zip code, or VIN sequence.

Dealers should perform this repair on all unsold vehicles before retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair.

VIN lists may contain confidential, restricted owner name and address information that was obtained from the Department of Motor Vehicles of various states. Use of this information is permitted for this notification only and is strictly prohibited from all other use.

Additional Information

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Service / Field Operations FCA US LLC

This notice applies to your vehicle,

[Model Year and Model]

VIN XXXXXXXXXXXXXXXXXXXX

47B

LOGO

VEHICLE PICTURE

YOUR SCHEDULING OPTIONS

- 1. RECOMMENDED OPTION**
Call your authorized Chrysler / Dodge / Jeep® / RAM Dealership
- 2. Call the FCA Recall Assistance Center at 1-800-853-1403.** An agent can confirm part availability and help schedule an appointment.
- 3. Visit recalls.mopar.com, scan the QR code below, or download the Mopar Owner's Companion App.**

QR Code

Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity.

DEALERSHIP INSTRUCTIONS

Please reference CSN 47B.

CUSTOMER SATISFACTION NOTIFICATION

Oil Pump

Dear [Name],

At FCA US LLC, we recognize that the success of our business depends on the satisfaction of our customers. We are constantly monitoring the quality of our products and looking for opportunities to improve our vehicles even after they are sold. Because your long-term satisfaction is important to us, we are contacting you on important improvements we would like to make to your vehicle ^[1]. This will be done at no charge to you.

We are recommending the following improvements be performed on certain [2023 Model Year (WS) Wagoneer/Grand Wagoneer] vehicles.

WHY DOES MY VEHICLE NEED REPAIRS?

The oil pump on your vehicle may have an incorrectly installed spring which can dislodge and cause oil starvation to the engine, resulting in a no start condition.

HOW DO I RESOLVE THIS CUSTOMER SATISFACTION NOTIFICATION?

FCA US will repair your vehicle free of charge (parts and labor). To do this, your dealer will replace the oil pump. The estimated repair time is about 10 hours. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Please bring this letter with you to your dealership.

**TO SCHEDULE YOUR FREE REPAIR,
CALL YOUR CHRYSLER, DODGE, JEEP OR RAM DEALER TODAY**

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit www.fcarecallreimbursement.com to submit your reimbursement request online. ^[2] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the repair performed.

We apologize for any inconvenience, but are sincerely concerned about your satisfaction. Thank you for your attention to this important matter.

Customer Assistance/Field Operations
FCA US LLC



Mr. Mrs. Customer
1234 Main Street
Hometown, MI 48371

[1] If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

[2] You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.