

**RAPID UPDATE**

FROM: Maserati TSO

TO: Maserati Network



**Maserati**

PERSONAL SERVICE LAB

MASTERS OF CARE

# Rapid Update 814 Grecale – Brake Disc Noise



DATE: January 27, 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to replace both front brake discs.

**VEHICLES INVOLVED:** (M182) Grecale MY25 MHEV

Some vehicles may have been equipped with brake discs that exhibit surface roughness outside Maserati specifications. This condition may cause a whistling noise during braking.

**Braking performance is not affected.** Because this is solely an acoustic issue, the Customer may not notice any noise, especially on vehicles with low mileage.

**Correction:**

- **Unsold in-stock vehicles:** Replace both front brake discs only.
- **Customer vehicles only:** Replace both front brake discs including the front brake pads.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

**Please read and review this bulletin first before ordering parts and/or starting the procedure.**

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati Americas  
Aftersales Dept.

# Technical Procedure



All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to confirm that the vehicle is included in this campaign and that the repair has not already been completed.

2. **Replace Both Front Brake Discs**

Replace the right- and left-hand front brake discs following the procedures in the workshop manual:

- **4.10.001** – Front Right Brake Disc: Detachment/Reattachment or Replacement
- **4.10.002** – Front Left Brake Disc: Detachment/Reattachment or Replacement

3. **Replace Front Brake Pads (Customer Vehicles Only)**

For Customer vehicles that have accumulated mileage with the non-compliant discs, replace the front brake pad kit at the same time. Follow the procedure in the workshop manual:

- **4.10.005 FRONT BRAKE PADS Replacement**



4. **Reassemble Components**

Reinstall all components by reversing the disassembly steps.

5. **Complete the Procedure**

Once the repair is complete, the vehicle can be released.

## Parts Information

Order the following parts per VIN:

Description	Part number	Amount
FRONT BRAKE DISC MHEV	670156762	2

**IMPORTANT NOTE: CUSTOMER vehicles only, order the pad kit at the same time, referring to the parts catalog to order the correct component based on the vehicle VIN.**

Description	Part number	Amount
GRECALE V-SLOT PADS KIT (ROW)	673016578	1
(SPECIAL) HEXALOBATE SCREW	675001495	4
<b>Or</b>		
FRONT BRAKE PADS KIT (US ME)	673016700	1
(SPECIAL) HEXALOBATE SCREW	675001495	4

## Warranty claim Information

Please complete the warranty request as follows:

Description	Code
Rapid Update Number	814
Warranty code	23
Error code	063
Component Code	4.10.001
Operation Code	
<ul style="list-style-type: none"> <li>▪ Replacement <b>ONLY Discs (both)</b></li> <li>▪ Replacement of <b>CUSTOMER</b> vehicles (Discs + PADS)</li> </ul>	4.10.001.A (0.55 h) 4.10.001.B (0.80 h)