



Service Bulletin

Bulletin No.: PIT5812F

Date: January, 2026

PRELIMINARY INFORMATION

Subject: Grind Noise From Brakes

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2021 - 2023		All	All	All	All
GMC	Terrain	2021 - 2023		All	All	All	All

Involved Region or Country	North America
Condition	Grinding noise on brake apply cold that dissipates after a few stops.
Cause	New no copper pad composition.

Correction

Engineering has determined that the performance of the brake pads on these vehicles is the same as we have experienced with the materials on other platforms and no changes are planned to these currently. If you are experiencing excessive noise issues, follow the published brake noise diagnostics.

Version	7
Modified	<p>02/02/2021 - Created on.</p> <p>05/10/2021 - Revised to add models.</p> <p>06/30/2021 - Removed Colorado and Canyon models due to the release of 21-NA-142</p> <p>03/15/2022 - Added 2022 model year</p> <p>02/24/2023- Added 2023 model year and expected resolution date.</p> <p>08/18/2024 - Updated to add model year 2024</p> <p>01/29/2026 - Updated to note the end the engineering review</p>

