

Bulletin #: C32-0126-0606		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: January 21, 2026		Supersedes:	



BMW PARTS BULLETIN

TEC826 TRIM RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following affected part numbers:

52 10 7 885 235

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far missing foam strips. Parts containing foam strips shown in image below are ok for use.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC826 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC826 is valid from January 21, 2026, through February 04, 2026. The deadline for filing a claim under TEC826 is February 04, 2026. All parts must be returned to your facing RDC no later than February 18, 2026.

Please reorder the same part number as needed.

