



SSM 54530 2021 Escape - "Tire Mobility" Message Displayed In The Message Center Of The Instrument Panel Cluster - Built On or Before 9-Feb-2021

Some 2021 Escape vehicles built on or before 9-Feb-2021 may exhibit a "Tire Mobility" message in the message center. This may be due to the software in the instrument panel cluster (IPC). To correct the condition, download and run the "IPC – Instrument Panel Cluster (IPC) Configuration" application in the Ford Diagnostic and Repair System (FDRS) scan tool. If asked if the original module is still installed, answer NO. For claiming, use causal part 10849 and labor operations 12651D and 12651D4.