



## **SSM 54531 2025 F-150/Bronco Sport/Maverick - Media Bin USB Port Illumination No Longer Equipped**

2025 F-150/Bronco Sport/Maverick vehicles are no longer equipped with illumination around the universal serial bus (USB) ports within the media hub located in the instrument panel and/or forward section of the floor console. The lack of illumination around the USB ports is not a defect or fault and the replacement of any parts is not a warrantable repair. Confirm media hub operation by plugging a device into the USB port and confirm it connects to the vehicle's entertainment system and charges the device. The media hub provides increased charging compared to prior model years. Do not submit a claim for this condition.