

**In-Vehicle / In-App Communication
Service Action Notification-Reminder
22 Jan 2026**

Title	Text	Short Text	Pop-Up
<p>Service Action: Control Unit - Both Front Light Electronics</p>	<p>The headlamp control module(s) may not have been produced to specifications. As a result, the headlamp(s) may not function as designed. If this were to occur, it would typically occur at vehicle start and only affect one headlamp. In an extremely rare case, it could affect both headlamps.</p> <p>Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer.</p>	<p>Service Action: Control Unit - Both Front Light Electronics. Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>	<p>Service Action: Control Unit - Both Front Light Electronics. Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>
<p>Service Action: Control Unit - Right Front Light Electronic</p>	<p>The headlamp control module(s) may not have been produced to specifications. As a result, the headlamp(s) may not function as designed. If this were to occur, it would typically occur at vehicle start and only affect one headlamp. In an extremely rare case, it could affect both headlamps.</p> <p>Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer.</p>	<p>Service Action: Control Unit - Right Front Light Electronic. Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>	<p>Service Action: Control Unit - Right Front Light Electronic. Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>
<p>Service Action: Control Unit - Left Front Light Electronic</p>	<p>The headlamp control module(s) may not have been produced to specifications. As a result, the headlamp(s) may not function as designed. If this were to occur, it would typically occur at vehicle</p>	<p>Service Action: Control Unit - Left Front Light Electronic. Contact an authorized MINI dealer</p>	<p>Service Action: Control Unit - Left Front Light Electronic. Contact an authorized MINI dealer at</p>

**In-Vehicle / In-App Communication
Service Action Notification-Reminder
22 Jan 2026**

<p>start and only affect one headlamp. In an extremely rare case, it could affect both headlamps.</p> <p>Contact an authorized MINI dealer at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer.</p>	<p>at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>	<p>your earliest convenience to get your vehicle repaired for FREE. Dealer locator: miniusa.com/dealer</p>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------