

Intermittent Connections and ECU Fault Codes



Topic Background:

1. Affected models: Freightliner eCascadia, Cascadia, Fifth Gen Cascadia, eM2, Western Star 47X, 49X
2. Symptoms may include intermittent connections, grounding, and other wiring related issues
3. This issue is detectable through issues like vehicle not starting, ICU messages, and telltale lamps.

Progress Updates:

1. Continuing to gather fault code field data
2. Fix as fail

Topic Resolution Info:

1. Improved electrical connection verification procedures at plants
2. Additional PDI steps added