

## SSM000017 - HIGH-SPEED COOLANT FAN OPERATION - 2.0L P4 ENGINE ONLY

### Range Rover

- 20-25MY RR Velar
- 20-25MY RR Evoque

### Defender

- 20-25MY Defender

### Discovery

- 20-25MY Discovery
- 20-25MY Discovery Sport

### Jaguar

- 20-25MY E-PACE
- 20-25MY F-PACE
- 20-24MY XF
- 20MY XE

### Customer Voice:

- *"After I shut my vehicle off, I can hear the fan continue to run at high speeds."*

### Technical Description:

- New PCM software to change the behavior of the cooling fans after engine shutdown to a more acceptable level.

### Action:

- The software has been released through TOPIx and also with SOTA 4.3.4.
- When a client is concerned about this condition, please start a new workflow in TOPIx with this concern of cooling fan noise.
- The workflow will direct you to the new PCM software update after all preliminary checks.
- To validate that the software has corrected the condition, please run the vehicle to normal operating temperature and then shut off the ignition. Fan should run at a moderate speed and then shut off.

