



Service Bulletin

Bulletin No.: PIT6467A

Date: February, 2026

PRELIMINARY INFORMATION

Subject: SES MIL / Fuel Gauge Drops To Empty / Stalls Due To Running Out Of Fuel / DTCs P3261 P3262 P3263

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 3500 HD	2025 - 2026		All	All	6.6L L8T	All
GMC	Sierra 3500 HD	2025 - 2026		All	All	6.6L L8T	All

Involved Region or Country	North America
Condition	Some customers may comment on any of the following: <ul style="list-style-type: none"> - SES MIL without any drivability issues with DTC's P3261, P3262, P3263 - Truck runs out of fuel with the fuel gauge indicating there is still fuel in the tank - Fuel gauge defaulting to empty, but there is still fuel in the rear tank
Cause	The cause of this condition could be the rear tank is not transferring fuel to the front tank.

Correction

Do not replace any parts at this time.

Engineering is currently investigating

The PI will be updated or replaced with a TSB once a determination has been made.

Version	2
Modified	12/16/2025 — Created. 2/2/2026 — Updated Correction.

