

Type: Bulletin

Year: 2026

System: exterior (78)

Sequence: 01

Title: B-pillar applique Fastener updates



Applicability: MY2025 Revero, GS-6, Revero GT and GTS

Market Region: All

PRIORITY: On complaint


PURPOSE: Update fasteners as a field fix

When complaints of sticking door glass on the b-pillar, or wind noise is considered, replacement to updated production fasteners is required for the best repair. Removal is as described in this bulletin. This will apply to both sides of the vehicle, replace fasteners for both sides when vehicle concern is present even if on only one.



Used in 2 positions per side

NEW



C144830407200 – Push Nut, provides better retention and fitment of B–Pillar Applique

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Bulletin

Year: 2026

System: exterior (78)

Sequence: 01

Title: B-pillar applique Fastener updates

Applicability: MY2025 Revero, GS-6, Revero GT and GTS


Market Region: All

Remove the B-pillar applique (Fig 1). The passenger (right) side will disassemble and reassemble same as the driver (left side shown). Retain any plastic washers used in previous assembly.

Note: Additional plastic washers can be used as shims to achieve flushness to door glass. Do not exceed two washers per fastener.



Remove the installed push nuts, and replace with C144830407200 push nuts (Fig 2). Reassembly torque for the b-pillar fastener screws is 2.5 +/-0.5Nm (T20 size in Fig 3).



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Bulletin

Year: 2026

System: exterior (78)

Sequence: 01


Title: B-pillar applique Fastener updates

Applicability: MY2025 Revero, GS-6, Revero GT and GTS

Market Region: All

Open both doors to access the seal bottom, pull it up to reveal T20 screws (Fig 4). Remove the fasteners (Fig 5 and Fig 6), and pull up gently and the top clip will release (Fig 7).

Note: watch for any plastic shims that may fall, you will reuse these to maintain established fitment.






Remove the old in body clips (Fig 8).

Use a small pick tool to catch the inside of the clip and wiggle it out (Fig 8 and Fig 9).

Insert the new clips (these are very small Fig 10, and Fig 11, Fig 12)

Using a shim to apply pressure to the clip to pop it in place is helpful.





Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Title: B-pillar applique Fastener updates


Applicability: MY2025 Revero, GS-6, Revero GT and GTS

Market Region: All

Hold the B-pillar applique in place and align the screws to the new clips, and place washers behind on the screw as it is assembled, do not tighten one side fully until both are holding plastic shims. Once seated, begin to tighten down, and press in the upper part of the applique so it snaps the clip into the upper b - pillar (Fig 13). Proceed to torque the screws to the appropriate measurement in Fig 14 (2.5 +/- 0.5Nm) Check flushness to the door glass as below (Fig 15).



The b-pillar should now sit as flush as specification with minimal adjustment expected. (Fig 16 and Fig 17)



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Type: Bulletin

Year: 2026

System: exterior (78)

Sequence: 01

Title: B-pillar applique Fastener updates

Applicability: MY2025 Revero, GS-6, Revero GT and GTS

Market Region: All

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
C144830407200	NUT-PUSH-IN 3.9 X 7.0 X 7.0 X 1.25	4

Please contact the parts department (parts@karmaautomotive.com) and order this part by email if not available in on-line at time of repair.

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART: (use one of the parts for the complaint)

PART NUMBER	DESCRIPTION
C131179103105	Assembly - Applique- B-Pillar LH

LABOR CODES: (use one appropriate for the part(s) replaced)

CODE	DESCRIPTION	TIME	DEFECT CODE
78-15-03-10	B – pillar applique updated fasteners	0.4	78-15-03-17

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for four (4) years from the in-service date or 50,000 miles for Model Year 2025 Revero, please see each model year warranty manual for warranty details.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.