

In-Vehicle / In-App Communication
Service Action Notification-Reminder
5 Feb 2026

Title	Text	Short Text	Pop-Up
Service Action: Radio/IHKA Control Panel	It was found that a radio IHKA control panel without a CD slide compartment has been installed due to a logistics error in production. A CD cannot be inserted and the radio IHKA control panel should therefore be replaced. Contact authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.	Service Action: Radio/IHKA Control Panel. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer	Service Action: Radio/IHKA Control Panel. Contact an authorized BMW center at your earliest convenience to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer