

Bulletin #: C32-0226-0614		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: February 03, 2026		Supersedes:	



BMW PARTS BULLETIN

TEC836 REAR BUMPER RETURN

TAKE ACTION

BMW AG has requested the return of the following part number:

51 12 8 058 060

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC836 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC836 is valid from February 03, 2026, through February 17, 2026. The deadline for filing a claim under TEC836 is February 17, 2026. All parts must be returned to your facing RDC no later than March 03, 2026.

Please refer to EPC for replacement part number.