

Bulletin #: C32-0226-0620		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: February 23, 2026		Supersedes:	



BMW PARTS BULLETIN

TEC844 KLE CONTROL UNIT RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

61 44 5 A60 2F9

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far missing MHD on component label and on BMW parts label. Parts containing the MHD on component label and BMW parts label are ok for use. (Please see images below)

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC844 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC844 is valid from February 23, 2026, through March 09, 2026. The deadline for filing a claim under TEC844 is March 09, 2026. All parts must be returned to your facing RDC no later than March 23, 2026.

Please reorder the same part as needed.

