




SIB 51 04 26

DEPRESSION ON TOP OF THE INSTRUMENT PANEL

2026-02-24

MODEL

E-Series	Model Description
G05	X5 Sports Activity Vehicle as of SoP (start of production)
G07	X7 SAV as of SoP

SITUATION

A slight depression or outline (circled) may be visible on the top passenger side of the instrument panel.

CAUSE

This outline is created by the perforated edge for the passenger side air bag. Due to normal variations designed in vehicles, this outline may be more noticeable in other vehicles.

CORRECTION

Do not replace any parts for this situation.

PROCEDURE

This is an Info only Bulletin

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
--------------------	---

