

WSU3 Workshop Campaign – Replacing air-conditioning compressor shield

WSU3 Workshop Campaign - Replacing air-conditioning compressor shield

ID Number	WSU3
Model(s)	Panamera (YAA/YAB)
Model Year(s)	2025 - 2026
Number of Affected Vehicles	129
VIN List	Attached below
Issue Description	On the affected vehicles, there is the possibility that a shielding plate was installed on the air-conditioning compressor whose weld points do not have the required strength.
What should Porsche Centers do?	Please arrange for the measure to be carried out on affected vehicles as soon as possible. As of the time of this posting (2/11/26) the remedy is immediately available.
Parts Status	Status 1 - Order as needed
TI	WSU3

Warranty processing

Validity:

The workshop campaign is carried out until the date maintained in PCSS and then closed.

Please note that warranty claims can only be processed up to this date.

Scope 1: Replacing air-conditioning compressor shielding plate

Damage Code	WSU3 66 000
Repair Code	2
Working time	544 TU

WSU3 Workshop Campaign – Replacing air-conditioning compressor shield

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [VIN_List_Report_WSU3_2026-02-11_V4.xlsx](#)