

February 28, 2026

Version 6

Warranty Extension: Customer Support Program For Driver's Airbag Inflator for 2013-14 ILX Hybrid and Other Listed Years and Models (Expired February 28, 2026)

The warranty coverage under this extension expired on February 28, 2026.

Repair orders dated on or prior to February 28, 2026 remain eligible and should reference the warranty claim information below.

APPLIES TO

Year	Model	Trim Level	VIN Range
2013–14	ILX Hybrid	ALL	Check the iN VIN status for eligibility.
2013–15	ILX	ALL	Check the iN VIN status for eligibility.
2007–15	RDX	ALL	Check the iN VIN status for eligibility.
2005–12	RL	ALL	Check the iN VIN status for eligibility.
2009–14	TL	ALL	Check the iN VIN status for eligibility.
2010–13	ZDX	ALL	Check the iN VIN status for eligibility.

WARRANTY CLAIM INFORMATION

- To avoid non-payment of warranty claims, the new airbag module part number and serial number must be included in each claim.
- To avoid a warranty claim being charged back to your dealership, follow the normal warranty part retention rules. American Honda may call in the original airbag module.
- The serial number is encoded into the bar code label attached to the outside of the box. If your dealership uses a scanner, you can scan the serial number into the claim.
- The part number is encoded into a barcode attached to the outside of the box. If your dealership uses a scanner, you can scan the part number into the claim.
- If you confuse the serial number and part number when entering the claim information, your claim will automatically be rejected.
- You must enter a DTC in the DTC field of the warranty claim.
- The FRT includes time for the inspection and replacement of the airbag module.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
7521M5	2013-14 ILX Hybrid	0.6 hr	6T200	C1200	77810-TK6-A50ZA
7521M5	2013-15 ILX	0.6 hr	6T200	C1200	77810-TX6-A50ZA
7521M5	2007-15 RDX	0.5 hr	6T200	C1200	77810-STK-A20ZA
7521M5	2005-12 RL	0.5 hr	6T200	C1200	77810-SJA-A20ZC
7521M5	2009-14 TL	0.5 hr	6T200	C1200	77810-TK4-A20ZA
7521M5	2010-13 ZDX	0.5 hr	6T200	C1200	77810-TK4-A20ZA

Skill Level: Repair Technician

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.