



Service Bulletin

American Honda Motor Co., Inc.

CRF300L #1
Revised: February 2026

EMISSION RECALL

2021-2025 CRF300L/LA/LDA FUEL SYSTEM

(This bulletin has been revised to update expected parts availability.)

NEW

BACKGROUND

Honda is launching an **EMISSION RECALL** on **ALL 2021-2025 CRF300L/LA/LDA motorcycles**. A fuel permeation test revealed that the fuel system does not meet regulatory standards. The fuel system has a lower than expected permeation value and is not within emission certification compliance.

AFFECTED UNITS

As of October 8, 2025, you **MUST NOT SELL ANY NEW or USED** 2021-2025 CRF300L/LA/LDA motorcycle until it is repaired according to forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **iN**.
- To manage your affected new inventory, use your dealer *eResponsibility Report* on **iN**.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected motorcycles in April 2026. Customers will be informed that their motorcycle is affected by this emissions-related defect. Once parts become available, customers will be notified by a second letter to make an appointment with an authorized Honda dealer for repair.

PARTS INFORMATION

Parts needed for the repair are expected in August 2026 and can be ordered according to the instructions in the forthcoming Service Bulletin. Dealers will be notified by **iN** message once parts become available.

SERVICE BULLETIN

CRF300 #1, which includes all the information relating to this Emission Recall, is expected to be issued in August 2026.

FLOORING SUPPORT

Due to the delayed availability of parts, American Honda will issue a prepaid flooring credit for all new, unregistered CRF300L/LA/LDA motorcycles in dealer inventory. For details, refer to the *Quality Issue Flooring Support* bulletin #26-0050 found on the **iN** under Sales >Sales Bulletins.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.

1 of 1