

Parts



Mazda North American Operations
Irvine, CA 92718-2906



REFERENCE NO: RF-26-01

DATE: 02/10/2026

SUBJECT: Coolant Control Valve Design Change Supersession (Multi-Model)

The coolant control valve updated part is now available and **supersedes** PYFD-15-16ZA. As a result, PYFD-15-16ZA is no longer available.

PW5S-15-16Z is supplied with a dummy plug pre-installed.

Critical Installation Requirement: When replacing PW5S-15-16Z, the Powertrain Control Module (PCM) **must** also be updated to the latest software version. Failure to perform the PCM update may result in drivability concerns or diagnostic trouble codes.

To confirm the applicable vehicle models and required software level, refer to the current [Technical Service Bulletin \(TSB\) in MGSS or the SSPD8 repair instructions and software level information.](#)