

STEERING REQUIRES STEADY CORRECTION FORCE

Customer Voice:

- “I have to constantly correct the steering to remain in lane on a straight road.”

Technical Description:

- This may be caused by Electric Power Assisted Steering (EPAS) system that has not yet adapted to the vehicle. Learning is enabled automatically during straight-line highway driving. Approximately 200 miles (320 kilometers) of driving is required to adapt to the vehicle and apply full compensation

Status:

- On a new vehicle or on vehicles where the steering gear has been replaced, the steering adaption will be learning for the first 200 miles.
- SSM000021 has been published to provide repair guidance.

Range Rover

- 22MY-On Range Rover
- 23MY-On RR Sport
- 21MY-On RR Evoque
- 21MY-On RR Velar

Defender

- 21MY-On Defender

Discovery

- 21MY-On Discovery Spor
- 21MY-On Discovery Spor

Jaguar

- 21MY-On F-PACE

