



SERVICE BULLETIN

Vermeer Corporation

Environmental
Pella, Iowa 50219 USA

FIELD CAMPAIGN SERVICE BULLETIN

SVC2026-034

DATE: 2026 February 26

CAMPAIGN
TYPE:

Mandatory-Product Compliance
DEALER INSPECTION ONLY

CAMPAIGN
CATEGORY:

Kit and Bulletin

MACHINE/ ATTACHMENT MODEL(S):	SERIAL NUMBERS:		Kit version
	Included	Excluded	
BC1000XL	24472, 26212, 28412, 35711	None	IK01
HG4000G2	101, 50031, 50066	None	IK01
HG6000	2005, 2014, 2017, 2021, 50014	None	IK01
HG6000TX	1087, 2015, 2018 – 2022, 2025	None	IK01
HG6800TX	131, 1103, 1137	None	IK01
LS3600TX	101, 104, 105, 108, 109, 114	None	IK01
SC48TX	112	None	IK01
SC60TX	2775, 2793, 4103, 4110, 4114, 4115	None	IK01
TG400ATX	208	None	IK01
TG5000	1021, 1023, 1024, 1032, 1039, 2002, 2011, 2015, 50001, 50013, 50016, 50021, 51008	None	IK01
TG7000	1070, 2014	None	IK01
WC2300XL	2002, 2027, 2028, 2031, 2033, 50005	None	IK01

Subject:**Engine and Exhaust
Components Serial Data
Collection Kit
(IK004661)****Background:****SERIAL DATA MISSING OR MISRECORDED**

Affected units left the factory with missing or misrecorded serial data for the engine, exhaust aftertreatment module or DEF tank module.

Solution:**IMMEDIATE MACHINE INSPECTIONS REQUIRED**

IK004661 has been created to require inspection of affected units to collect and submit digital photos of serial tags for the aforementioned components. **These inspections must be carried out as soon as possible.**

When the dealer inspection report is returned to Product Safety, each machine's Vermeer Warranty campaign record will be updated as shown below. If a dealer is the machine owner, please also complete and submit the inspection report to safetyform@vermeer.com.

Campaign #	Campaign description	Status	Code meaning
SVC2026-034	ENGINE AND EXHAUST COMPONENTS SERIAL DATA COLLECTION KIT	OPEN	Dealer inspection report has not been returned to Product Safety.
SVC2026-034	ENGINE AND EXHAUST COMPONENTS SERIAL DATA COLLECTION KIT	DONE	Dealer inspection report has been returned to and approved by Product Safety.
IK004661	ENGINE AND EXHAUST COMPONENTS SERIAL DATA COLLECTION KIT	OPEN	Dealer inspection report has been returned to and approved by Product Safety and a campaign reimbursement claim can be filed.

DEALER PARTICIPATION**REVIEW REPORT, ORDER KITS, CONTACT CUSTOMERS**

1. **Review report.** Reports will be emailed during the week of February 26, 2026, to dealerships shown in our records which have units in their territory affected by this alert. Please review the report for accuracy, including owner and/or address changes.

If the information contained in the report is NOT correct, please notify the product safety and compliance department on or before March 11, 2026, at:

Telephone: 641-621-7060

Fax: 641-621-8562

Email: productsafety@vermeer.com

2. **Dealership will complete the dealer inspection form** that is located on page 4 of this bulletin and return to safetyform@vermeer.com **with photos of the serial data for the engine, exhaust aftertreatment module, and DEF tank module.** Refer to IK004661 inspection procedure instructions.

3. **Contact your affected customer(s)** to schedule a mutually acceptable time to inspect their machine(s). **Note:** Letters will be sent to the customer(s) on or about **March 12, 2026**. *Also refer to Owner Notification section below.*



**DEALER
INSPECTION
REPORT**



**PRODUCT
COMPLIANCE**

First Notice

**Engine and Exhaust Components
Serial Data Collection Kit
(IK004661)**

1.	Perform machine inspection following IK004661 kit instructions. Take photos of serial tags for the engine, exhaust aftertreatment module, DEF tank module, and VIN plate. Ensure serial numbers are clearly readable in each photo.		
	Model:	VIN:	
	Machine owner contact:		
	Machine owner company:		
	Machine owner address:		
2.	Take a clear picture of each serial tag.		
Engine serial number			
Exhaust aftertreatment module			
	DEF tank module		
3.	Email completed form to: safetyform@vermeer.com . Attach photos of serial data for the engine, exhaust aftertreatment module, DEF tank module, and VIN plate. If collecting serial data for multiple units, only send the photo set of one unit per email.		
	Dealer Inspection Results Report completed by:	X	
	Print name:		
	Dealer's company name:		
	Dealer's city, state/province:		

If you have any questions concerning the installation of IK004661, please contact the environmental service department.

REIMBURSEMENT

Kit installation. Upon completion of each machine inspection, a campaign warranty claim must be submitted to the warranty department for reimbursement of the cost of labor to install the kit. Labor hours to install: 1.0 hours.

This kit will reimburse labor hours as follows:

- **SVC2026-034:** Inspection Only – no reimbursement. Inspection form will need to be completed and sent to safetyform@vermeer.com. Await approval from Product Safety prior to filing a claim.
- **IK004661:** 1.0 hours for kit inspection

Travel will be paid up to \$200 (\$1 per mile with a \$200 max round trip) with copy of work order attached for retailed machines not in dealer inventory. If dealer repairs more than one machine at same location on one trip, travel will only be paid on one of the model/VINs.

Note: *Future notices to dealers and owners are dependent upon the receipt of warranty claims.*

OWNER NOTIFICATION

Sample letter: Included at the end of this bulletin is a sample letter which will be sent by Vermeer Corporation directly to the owners on or about March 12, 2026. Owner notice translations will be provided in the following languages:

• Brazilian Portuguese	• Italian
• French	• Japanese
• German	• Spanish

All translated owner notices will also include owner notification in English.

This owner notification/letter instructs the owner **to contact their local dealership** to arrange for a time to have their unit inspected.

We regret any inconvenience these corrective measures may cause you. The required work is to ensure compliance with **40 CFR 1068.261**, affirming engines and exhaust components sold to Vermeer were installed in a certified configuration.

PRODUCT COMPLIANCE DEPARTMENT

Attachment:
IK004661 Kit Instructions

Completion schedule: ☐ Product Safety Alert: Install immediately ☒ Product Compliance: Install immediately ☐ 90 days from MM/DD/YYYY ☐ 180 days from MM/DD/YYYY ☐ 1 year from MM/DD/YYYY ☐ Only units within standard limited warranty period ☐ N/A	Reimbursement: ☐ Product Safety Alert ☒ Product Compliance ☒ All units listed above with less than __ hours or warranty start date in the last __ months ☐ Parts ☒ Labor paid (Labor code: SB26) ☐ Only units within standard limited warranty period ☐ No reimbursement
---	---

Internal reference: TREAD Act Code <i>(Choose one or more applicable codes)</i>	☒	--	Not applicable	☐	12	Exterior lighting
	☐	02	Suspension	☐	16	Structure
	☐	03	Service brake system, hydraulic	☐	17	Latch
	☐	04	Service brake system, air	☐	19	Tires
	☐	05	Parking brake	☐	20	Wheels
	☐	11	Electrical	☐	21	Trailer hitch

Dealer Distribution:

☐ Domestic
☐ International
☒ Both



SAMPLE OWNER LETTER

Product Safety Department
Vermeer Corporation
1210 Vermeer Rd East
Pella, Iowa 50219 USA
productsafety@vermeer.com



PRODUCT COMPLIANCE

First Notice Engine and Exhaust Components Serial Data Collection Kit (IK004661)

Model: «Model»

Serial #: «SerialN»

March 12, 2026

Dear «MODEL» owner:

According to our records, you currently own a Vermeer «MODEL». The model and serial number are shown at the top center of this letter.

SERIAL DATA MISSING OR MISRECORDED

Affected units left the factory with missing or misrecorded serial data for the engine, exhaust aftertreatment module or DEF tank module.

IMMEDIATE MACHINE MODIFICATION REQUIRED

IK004661 has been created to require inspection of affected units to collect photos of serial tags from the aforementioned components. **This inspection must be completed as soon as possible.**

Please contact your authorized, independent Vermeer dealer immediately to arrange a mutually acceptable time and location to have your unit inspected at no cost to you for labor or materials. If the Vermeer dealer travels to the unit to inspect the machine, costs may be incurred by the owner. **You must have your machine inspected to ensure product compliance.**

Contact your local Vermeer dealer: «Service_Dealer_Name»
«Serv_Dealer_Add1» «Serv_Dealer_Add2»
«Serv_Dealer_City» «Serv_Dealer_St» «Serv_Dealer_Zip»
«SERV_DEALER_COUNTRY»
Telephone: «Serv_Dealer_Phone»

If you no longer own this unit, please notify the product safety and compliance department at:

Toll-free: 800-829-0051, option 1

Telephone: 641-621-7060

Email: productsafety@vermeer.com

If possible, please provide the name and address of the new owner.

We regret any inconvenience that these corrective measures may cause you. The required work is to ensure compliance with **40 CFR 1068.261**, affirming engines and exhaust components sold to Vermeer were installed in a certified configuration.

Regards,
PRODUCT COMPLIANCE DEPARTMENT