

45-069: Cummins TSB 210203 Update

2/3/2026

 [Edit](#)  [Clone](#)

45-069

Cummins TSB 210203 Update

Subject

Cummins TSB 210203 Update

Whats New Abstract

Cummins TSB 210203 has been updated to remove the PACCAR suction side fuel filter part number from Table 1 as the filter is no longer compatible.

Revision

02/03/2026: Cummins TSB link was updated to the newest version with the PACCAR filter part number removed.

Condition

Cummins TSB 210203 has been updated to remove the PACCAR suction side fuel filter part number from Table 1 as the filter is not compatible.

Chassis Affected

Any Kenworth chassis with a Cummins PX-9 engine

Action

Information Only

Refer to Cummins TSB 210203 in the Links section or, for the latest version, in Cummins QuickServe.

Attachments

[Cummins TSB 210203](#)

Authored by: JB3

45-069: Cummins TSB 210203 Update

Number	 Edit  Clone
45-069	
Description	
Cummins TSB 210203 Update	
Subject	
Cummins TSB 210203 Update	
Date	
7/9/2024	
Revision	
02/03/2026: Cummins TSB link was updated to the newest version with the PACCAR filter part number removed.	
Condition	
Cummins TSB 210203 has been updated to remove the PACCAR suction side fuel filter part number from Table 1 as the filter is not compatible.	
Chassis Affected	
Any Peterbilt chassis with a Cummins PX-9 engine	
Action	
Information Only	
Refer to Cummins TSB 210203 in the Links section or, for the latest version, in Cummins QuickServe.	
Links	
Cummins TSB 210203	