



## **SSM 54631 2020-2026 Escape, 2022-2026 Maverick - 2.5L Duratec hybrid - Exhaust Heat Exchanger Workshop Manual (WSM) Service Procedure Update**

Some 2020-2026 Escape and 2022-2026 Maverick 2.5L Duratec hybrid vehicles may require various repairs on the exhaust system. This may require removal of the exhaust heat exchanger. WSM, Section 309-00 Exhaust System > 2.5L Duratec hybrid > Removal and Installation > Exhaust Heat Exchanger has been revised to eliminate the need to remove the muffler assembly. The procedure steps and labor times have been updated to reflect this adjustment.