



SSM 54641 2025-2026 F-Super Duty – Radio Intermittently Turns Off/No Audio During Snowplow Operation

Some 2025-2026 F-Super Duty vehicles properly upfitted with a snowplow kit following the guidelines in the Super Duty Body Builders Layout Book (located on the www.FordPro.com website > Resources > Body Builder Advisory Service (BBAS) > Publications) may experience a radio volume that temporarily turns off or decreases when the engine RPMs are raised above idle and the snowplow is operated. Ford is aware of this condition and is investigating a service solution. Component replacement is not expected to resolve this condition. Monitor Professional Technician System (PTS) for updates.