



SIB 65 08 26

AUTOMATE MY HABITS SETTINGS ARE LOST AFTER 25-07-5XX

2026-03-16

<input checked="" type="checkbox"/>	THIS REPAIR IS MOBILE FRIENDLY
-------------------------------------	--------------------------------

## MODEL

F74 (2 Series Coupe)	F95 (X5 M Sports Activity Vehicle)	F96 (X6 M Sports Activity Coupe)	G05 (X5 Sports Activity Vehicle)
G06 (X6 Sports Activity Coupe)	G07 (X7 Sports Activity Vehicle)	G09 (BMW XM Sport Activity Vehicle)	G20 (3 Series Sedan)
G22 (4 Series Coupe)	G23 (4 Series Convertible)	G26 (4 Series Gran Coupe)	G45 (X3 Sports Activity Vehicle)
G60 (5 Series Sedan)	G70 (7 Series Sedan)	G80 (M3 Sedan)	G82 (M4 Coupe)
G83 (M4 Convertible)	G87 (M2 Coupe)	I20 (iX Sports Activity Vehicle)	U10 (X2 Sport Activity Coupe)
U11 (X1 Sport Activity Vehicle)			

## SITUATION

After the software update to version ...25-07-5XX, existing activation points for the “Automate My Habits” function no longer work.

## CAUSE

Software changes to the “Automate My Habits” function in I-level ...25-07-5XX.

## CORRECTION

Activation points for the “Automate My Habits” function must be recreated.

## PROCEDURE

Due to a software change with the “Automate My Habit” function, any activation points saved on a HU-H5 vehicle will not transfer to a HU-H6 vehicle and vice versa.

If the activation points stop functioning, they will need to be deleted and recreated by the customer.

## CLAIM INFORMATION

This Service Information Bulletin provides technical and updated software-related information.

## FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

